

Model: DVK-300HD

Apr. 24, 2017 GB684N0

User Interface Software:

- **Version: 1.8**
- **File name: DVKeyHD_setup_1.8**

Issues

1. The mask is not always in the same place after rebooting the next day
 2. Keep enabling "SHOW ALPHA MATTE" if it has been ticked after re-booting
-

Apr. 08, 2016 GB684N0

User Interface Software:

- **Version: 1.7**
- **File name: DVKeyHD_setup_1.7**

Issues

Added RS-232 Remote Control function

Dec. 25, 2014 GB684N0

User Interface Software:

- **Version: 1.6**
- **File name: DVKeyHD_setup_1.6**

Issues

Corrected the problem with switching between Chroma and Luma settings

Jul. 15, 2014 GB684N0

User Interface Software:

- **Version: 1.5**
- **File name: DVKeyHD_setup_1.5**

Issues

1. Correction of the last setting save issue

When chrominance keyer / background color = blue, the failure rate is very high on this setting. When chrominance keyer/ background color = Green and the setting did not change, you can see the setting color value is incorrect so we need to select green / blue again then it will be a correct color.

2. Improved communication problems

Jun. 19, 2014 GB684N0

User Interface Software:

- **Version: 1.3**
- **File name: DVKeyHD_setup_1.3**

Issues

1. Some improvements regarding HDMI communication
 2. This version also includes all translations (Multi Language)
 3. One extra feature is MIRROR option available on preview output. Mirror makes it possible to easily operate talent during live presentations. Left hand still remains on the left in preview monitor for weather presenter. Generally this functionality always comes with all Chroma keyers. Enabling/disabling is available in the Configuration menu.
-